Niagara Falls Boulevard Niagara County, New York 2019 Removal Action Daily Report

Date: Monday, October 14, 2019

Personnel On-Site:

EPA OSC – Peter Lisichenko START V – Sean Quinn

ERRS Contractor: Guardian Environmental Services (GES)

Weather: Partly Cloudy, 10% chance of rain, Lo: 63°F, High: 71°F, Winds: 5-10 mph, due SSE, 86% humidity.

Health and Safety: Safety topics included: being aware of slips, trips, and falls, site traffic and heavy equipment awareness, cold stress, using proper personal protective equipment (PPE), and radiation hazards.

Activities Completed:

- 1. ERRS completed moving the perimeter fence around the work zone to ensure adequate space between work zones and the parking lot area.
- 2. Julies Toiles delivered two port-a-johns and a hand wash to the Site.
- 3. ERRS cleared vegetation in Area 12 in preparation for Site activities.
- 4. ERRS moved clean Soil from Area 12 to Area 09.
- 5. At the end of the work day, START V uploaded field data to the EPA internet share point site designated for the Site.

Planned Activities for October 15, 2019:

- 1. ERRS will begin to remove contaminated soil from Area 09.
- 2. START V will begin Site air monitoring at various locations to be determined at the start of each work day.
- 3. START V will begin screening soil in Area 09 via Ludlum 2241 with 3x3 NaI scintillator to ensure radiation contamination has been removed bellow the site-specific action level.

10/14/2019

Niagara Falls Boulevard Niagara County, New York 2019 Removal Action Daily Report

Soil Excavation Data:

Soil Volume Excavated Today (In Cubic Yards)	0
Cumulative Soil Volume Excavated (In Cubic Yards)	0
Total Number of Disposal Trucks Today	0
Total Number of Disposal Trucks To Date	0
Number of Backfill Trucks Today	0
Number of Backfill Trucks To Date	0

Niagara Falls Boulevard Niagara County, New York 2019 Removal Action Daily Report

Site Photographs



View of ERRS clearing vegetation near the tree line in Area 12.



A view of ERRS moving the perimeter fence to ensure the work zone is adequate in size.